

--	--	--	--	--	--	--	--	--	--



P.E.S. College of Engineering, Mandya - 571 401

(An Autonomous Institution affiliated to VTU, Belgaum)

Third Semester, B.E. - Mechanical Engineering

Semester End Examination; Dec. - 2015

Material Science and Metallurgy

Time: 3 hrs

Max. Marks: 100

- Note:** i) Answer any **FIVE** full questions, selecting **ONE** full question from each **unit**.
ii) Assume suitably missing data if required.

UNIT - I

- 1 a. Explain following terms,
- | | | | |
|---------------------------|-------------------|---------------------------|----|
| i) Unit cell | ii) Space lattice | iii) Co-ordination number | 10 |
| iv) Atomic packing factor | v) Diffusion. | | |
- b. Derive an expression for non steady state diffusion. 6
- c. A plate of iron is exposed to a carburizing atmosphere on one side and a decarburizing atmosphere on the other side at 800°C. The diffusion is steady state and diffusion coefficient is of $3 \times 10^{-11} \text{ m}^2/\text{s}$ at this temperature. Calculate the diffusion flux of carbon through the plate if the concentrations of carbon at positions of 5 and 10 mm beneath the carburizing surface are 1.2 and 0.8 kg/m³, respectively. 4
- 2 a. Show that Atomic packing factor for FCC is 0.74. 8
- b. Aluminium has FCC structure and an atomic radius of 0.143 nm. Calculate the volume of its unit cell in meters. 4
- c. Steel initially has a uniform carbon concentration of 0.25 wt% and is to be treated at 950°C. If the concentration of carbon at surface is suddenly brought to and maintained at 1.2 wt%, how long will it take to achieve a carbon content of 0.80 wt% at a position 0.5 mm below surface? The diffusion coefficient for carbon in iron at this temperature is $1.6 \times 10^{-11} \text{ m}^2/\text{s}$. 8

Table show Error function values

Z	erf (z)
0.35	0.3794
0.40	0.4284

UNIT - II

- 3 a. Draw stress – strain diagram for ductile material and explain the salient points. 8
- b. Define fracture toughness and give corresponding equation. 4
- c. With help of neat S – N diagram explain its significance. 8

- 4 a. Draw stress – strain diagrams for both ductile and brittle material and discuss the differences. 8
- b. List factors affecting fatigue life. 4
- c. Explain various stages of creep with help of neat diagram. 8

UNIT - III

- 5 a. What are solid solutions? Discuss factors governing formation of solid solution. 8
- b. Draw Iron carbon equilibrium diagram and label various phases present, temperatures and percentages of carbon on it. Also give the invariant reactions. 12
6. a. Explain the following terms, 8
- i) Phase ii) Component
- iii) Liquidus iv) Solidus
- b. Explain the steps involved in construction of TTT diagrams for plain carbon steel. 12

UNIT - IV

- 7 a. With help of phase diagram explain spheroidizing annealing process. 10
- b. With help of neat sketch explain method of obtaining Hardenability curves for steels. 10
- 8 a. Mention the purpose, explain the process and give the applications of martempering with help of phase diagram. 10
- b. Explain Age hardening of AL – CU alloys with help of phase diagram. 10

UNIT - V

- 9 a. Explain cathodic protection with help of neat sketch. 8
- b. Explain the following briefly, 8
- i) Polarization
- ii) Passivation
- c. List various methods of corrosion prevention methods and explain briefly any one. 4
- 10 a. Enumerate terms of the steel designation “SAE 1040”. 4
- b. Give the classification of plain carbon steel and mention its applications. 6
- c. Explain copper alloys with respect to composition, properties and applications. 10

* * * *