

Calculate the efficiency of motor and generator on full load.

Р	P17EE53 Page No 2	Page No 2			
6 a.	Explain how the moment of inertia of a DC motor can be estimated?	5			
b.	Explain the construction and operation of a permanent magnet DC motor.	5			
c.	 A 500 V shunt motor takes 8 A on no load. The armature and field resistance are 0.2 Ω and 250 Ω respectively when measured at room temperature. Neglect the effect of temperature rise find the efficiency of the machine when, i) Machine runs as a motor taking a line current of 90 A at 500 V ii) Machine runs as a generator delivering a line current of 90 A at 500 V. 	10			
	Stray load losses are about 1.2% of the output UNIT - IV				
7 a.	Discuss the various measures adopted in practice to make the waveform of large alternators to be closely sinusoidal.	10			
b.	A 3 ϕ , 10 pole, 600 rpm star connected alternator has 12 slots per pole with 8 conductors per slots and the winding is short chorded by 2 slots. The flux per pole contains a fundamental of 0.09 <i>wb</i> a third harmonic of 20% and fifth harmonic of 10% of the fundamental. Determine the rms values	10			

- 8 a. With usual notations with Phasor diagram and figures explain armature reaction in alternators for lagging and leading power factor loads.
 - b. A 6600 V alternator gave the following test results on OC and SC test :

0	8					
OC voltage: V	3100	4900	6600	7500	8300	
Field current: A	16	25	37.5	50	70	

A field current of 22 A is found necessary to circulate full load current on short circuit of the 10 armature. Calculate the full load regulation at 0.8 pF lagging by,

i) Ampere turn method

of phase and line voltages.

ii) Synchronous impedance method

UNIT - V

9 a. List the conditions to be satisified for successful parallel operation of 3¢ alternators. 3

7

10

10

- b. What are V and ^ curves? How to obtain them? Explain their significance.
- c. A 2000 V, 3φ, star connected synchronous motor runs at 1500 rpm. The excitation is constant and the corresponding open circuit voltage is 2 kV. The resisitance is negligible and the synchronous reactance is 3.5 Ω per phase . for an armature current of 200 A determine;
 i) Power factor

1) Power factor

- ii) Power input
- iii) Torque developed
- 10 a. With usual notations, derive an expression for the power output of a syllindrial rotor altenator connected to an infinite bus in terms of excitation voltage, bus voltage and load angle . Draw the phasor diagram.
 - b. Two identical 2000 kVA altenators operate in parallel. The governor of first machine is such that frequency drops uniformly from 50 Hz on no load to 48 Hz at full load, the corresponding speed drop is second machine is 50 Hz to 47.5 Hz

i) How will the two machines share a load of 3000 kW?

ii) What is the maximum load at unity power factor that can be delivered without over loading either machines?