U.S.N



P.E.S. College of Engineering, Mandya - 571 401

(An Autonomous Institution affiliated to VTU, Belagavi)

Fifth Semester, B.E. - Mechanical Engineering Semester End Examination; Feb. - 2021 CAD / CAM

Time: 3 hrs Max. Marks: 100

Course Outcomes

The Students will be able to:

CO1: Describe latest in-put and out-put devices used in CAD.

CO2: Explain modeling techniques and Solve problems on transformations.

CO3: Explain the basic components of NC system and Compare CNC machines.

CO4: Identify CNC machine components and cutting tool system used in CNC.


CO5: Develop CNC part program for different operations.

Note: I) PART - A is compulsory. Two marks for each question.

II) PART - B: Answer any <u>Two</u> sub questions (from a, b, c) for Maximum of 18 marks from each unit.

Q. No.	Questions	Marks	BLs COs	POs
	I : PART - A	10		
I a.	List the different types of plotters used in CAD	2	L1 CO1	PO3
b.	Define concatenation of transformation.	2	L1 CO2	PO2
c.	What is incremental coordinate system?	2	L1 CO3	PO1
d.	List the feed drives that are used in CNC machine tools.	2	L1 CO4	PO2
e.	Name the code for spindle stop and change in CNC.	2	L1 CO5	PO5
	II : PART - B	90		
	UNIT - I	18		
1 a.	With the help of a block diagram, explain product in Conventional manufacturing environment.	9	L2 CO1	
b.	With sketches, explain the two types of Stroke writing graphic terminals.	9	L3 CO1	PO2
c.	List the advantages and limitations of CAD / CAM.	9	L2 CO1	PO4
	UNIT - II	18		
2 a.	A square (Fig. 2a) with an edge length of 10 units is located in the origin			

2 a. A square (Fig. 2a) with an edge length of 10 units is located in the origin with one of the edges at an angle of 30° with the +*X*-axis. Calculate the new position of the square, if it is rotated about the *Z*-axis by an angle of 30° in the clockwise direction.



9 L3 CO2 PO2

Contd... 2

P18ME551				Page No 2	
b.	Discuss how solids are created using CS	G.	9	L2 CO2 PO3	
c.	With sketch give a brief description about	at Bezier curves.	9	L2 CO2 PO3	
	UNIT - III		18		
3 a.	Discuss about the basic components of N	9	L2 CO3 PO2		
b.	With block diagram, explain the machine control unit of CNC.			L2 CO3 PO3	
c.	With sketch, explain the three basic types of NC motion control systems.			L2 CO3 PO3	
	UNIT - IV		18		
4 a.	Explain tool change procedure using double gripper with sketches.		9	L2 CO4 PO2	
b.	b. With sketch, briefly describe the absolute encoder and incremental encoder			L2 CO4 PO3	
	used for rotary position measurement.			L2 CO4 103	
c.	Discuss about cutting tool materials used in CNC machine tools.		9	L2 CO4 PO2	
	UNIT - V		18		
5 a.	With sketches, explain tool length	compensation and cutter	radius 9	L2 CO5 PO4	
	compensation.			L2 CO3 TO1	
b.	With block diagram, explain the st	teps involved in the CN	NC part	L2 CO5 PO5	
	programming.			22 000 100	
c.	Write a manual NC part program for th	iven the			
	following data:				
	For milling	For drilling	9	L4 CO5 PO5	

Spindle speed : 2000rpm

Feed rate: 150mm/min

Assume all other data suitably.

Spindle speed: 500rpm

Feed rate: 375mm/min




Fig.5c