

| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|
| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|



P.E.S. College of Engineering, Mandya - 571 401

(An Autonomous Institution affiliated to VTU, Belgaum)

Third Semester, B.E. - Mechanical Engineering

Semester End Examination; Dec - 2016/Jan - 2017

Material Science and Metallurgy

Time: 3 hrs

Max. Marks: 100

- Note:** i) Answer **FIVE** full questions, selecting **ONE** full question from each unit.
 ii) Draw neat sketch wherever necessary and answer should be specific.
 iii) Assume suitably missing data, if any.

UNIT - I

- 1 a. Define: 4
 i) Unit cell ii) Space lattice.
- b. With the help of neat sketch, explain: 8
 i) BCC ii) FCC iii) HCP.
- c. Define Co-ordinate Number (CN) and Atomic Packing Factor (APF). And also give values of CN and APF for SC, BCC, FCC and HCP. 8
- 2 a. Give the classification of crystal imperfections. 4
 b. With the help of neat sketch, explain screw dislocation. 8
 c. State and explain Fick's law of Diffusion for steady state Diffusion. 8
 A plate of Iron exposed to carburizing atmosphere on one side and a decarburizing atmosphere on the other side at temperature 700°C. If a condition of steady state is achieved, calculate the diffusion flux of carbon through the plate. If the concentration of carbon at positions of 5 and 10 mm beneath the carburizing surface are 1.2 and 0.8 kg/m³ respectively. Assume coefficient of diffusion as 3×10^{-11} m/s at this temperature.

UNIT - II

- 3 a. With help of neat sketch explain engineering stress and strain and true stress and strain. 8
 b. What is plastic deformation? With help of sketch, explain any one of plastic deformation mechanism. 8
 c. List various properties under elastic and plastic deformations zones. 4
- 4 a. Explain various stages of ductile fracture with help of neat sketch. 8
 b. With help of creep curve, explain creep failure. 8
 c. Sketch and explain briefly various fatigue loads. 4

UNIT - III

- 5 a. Explain terms: 4
 i) Component ii) System iii) Phase and solubility.

- b. Give rules governing formation of solid solution. 8
- c. Draw a phase diagram for Eutectic system and label all its parts. 8
- 6 a. Draw a neat sketch of iron-carbon equilibrium diagram and label various phases reactions on it. 10
- b. Explain the various steps involved in construction of TTT diagram for eutectoid steel (0.8%C). 10

UNIT - IV

- 7 a. List various types of annealing and explain spheroidising annealing. 10
- b. Give the objectives of hardening and explain hardening process. 10
- 8 a. Explain joining end-quench test with suitable sketch. 10
- b. Explain participation hardening with help of Al-Cu phase diagram. 10

UNIT - V

- 9 a. Explain Galvanic cell corrosion and also mention few methods to control the same. 10
- b. Write a short note on:
 - i) Polarization 10
 - ii) Passivation.
- 10. Write short notes on any two :
 - i) Corrosion prevention methods 20
 - ii) Cathode protection
 - iii) Stress corrosion cracking.

* * *