P13I	3IP72 Page No			
	U.S.N			
P.E.S. College of Engineering, Mandya - 571 401 (An Autonomous Institution affiliated to VTU, Belgaum) Seventh Semester, B.E. – Industrial and Production Engineering Semester End Examination; Dec - 2016/Jan - 2017 Mechatronics Time: 3 hrs Max. Marks: 100 Note: Answer FIVE full questions, selecting ONE full question from each unit.				
1010	UNIT - I			
1 a.	With neat sketch, explain elements of closed loop system.			
b.	List out the advantages and limitations of mechatronics.			
c.	Explain with neat diagram, Engine Management System.			
2 a.	With neat sketch, explain eddy current proximity sensors.			
b.	Explain with diagram, working principle of automatic camera.			
c.	Discuss the evolution of mechatronics.			
	UNIT - II			
3 a.	Explain the following with sketches;			
	i) Diodes			
	ii) Thyristors.			
b.	Discuss MOSFET with sketches.			
4 a.	Explain the working principle of following D.C. motors;			
	i) Series wound motor			
	ii) Shunt wound motor.			
b.	Discuss the specification of stepper motor.			
	UNIT - III			
a.	Differentiate between microprocessor and micro controller.			
b.	With a neat diagram, explain the general microprocessor architecture.			
c.	Discuss on Data bus.			
a. h	Explain ROM, RAM and EPROM.			
b.	With neat diagram, explain micro controller. UNIT - IV			
a.	Explain:			
	i) AND gate ii) NOT gate and NAND gate with neat sketches.			
b.	Define number system with an example.			

P13IP72 Page No.			
Discuss the following :			
i) Low pass	ii) High pass	iii) Band pass filters.	10
		UNIT - V	
With neat diagram, explain flat and dove tail and friction guideways.			8
With neat sketch, explain recirculating ball screw and nut.			
Explain the concept of stick-slip phenomenon.			
. Define bearing. With neat sketch, briefly explain different types of bearing used in de			
spindle bearing.			
Explain the concept of preloading of ball nut.			
Summarize on planetary roller screw.			
	Discuss the follo i) Low pass With neat diagra With neat sketch Explain the cond Define bearing. spindle bearing. Explain the cond	Discuss the following : i) Low pass ii) High pass With neat diagram, explain flat and d With neat sketch, explain recirculatin Explain the concept of stick-slip pher Define bearing. With neat sketch, br spindle bearing. Explain the concept of preloading of the set of	Discuss the following :i) Low passii) High passiii) Band pass filters.iii) Low passii) High passiii) Band pass filters.UNIT - VWith neat diagram, explain flat and dove tail and friction guideways.With neat sketch, explain recirculating ball screw and nut.Explain the concept of stick-slip phenomenon.Define bearing.Unit - VExplain the concept of stick-slip phenomenon.Define bearing.Explain the concept of preloading of ball nut.

\* \* \*