U.S.N



P.E.S. College of Engineering, Mandya - 571 401

(An Autonomous Institution affiliated to VTU, Belagavi)

Fourth Semester, B.E. - Industrial and Production Engineering Semester End Examination; July/August - 2022 Manufacturing Technology - II

Time: 3 hrs Max. Marks: 100

Course Outcome

The Students will be able to:

- CO1: Identify lathe parts and explain its operations.
- CO2: Explain the drilling machine, its operations and distinguish shaper and planer.
- CO3: Describe the importance of milling machine and solve different types of indexing calculations.
- CO4: Describe the types of grinding machines and abrasive particles with its applications.
- CO5: Summarize surface finishing processes and explain importance of broaching and gear cutting.

Note: i) **PART-A** is compulsory. One question from each unit for maximum of 2 marks.

ii) **PART-B** Answer any **TWO** sub questions (from a, b, c) from each unit for a Maximum of 18 marks.

| O No | Owestions | Marilia | DI a | COa | DO |
|--------|--|-------------|------|-----|------|
| Q. No. | Questions I:PART - A | Marks 10 | DLS | COs | POS |
| I a. | Write the operations of lathe. | 2 | L1 | CO1 | PO1 |
| b. | List work holding devices in drilling machines. | 2 | L1 | CO2 | PO1 |
| c. | What is indexing? | 2 | L1 | CO3 | PO1 |
| d. | Define Grindability. | 2 | L1 | CO4 | PO1 |
| e. | List the classification of broaching machine according to method | 2 | Т 1 | CO5 | DO1 |
| | operation. | 2 | L1 | COS | POI |
| | II:PART - B | 90 | | | |
| | UNIT - I | 18 | | | |
| 1 a. | Draw a neat sketch of Lathe and explain briefly the different parts of a | 9 | 1.0 | CO1 | DO 4 |
| | lathe. | 9 | L2 | CO1 | PO4 |
| b. | During machining of C-20 steel with a cutting tool 0-8-6-7-10-70-1. The | | | | |
| | following data was obtained: | | | | |
| | i) Feed = 0.18 mm/rev ii)Depth of cut = 2 mm | | | | |
| | iii) Cutting speed = 120 m/min iv) Chip thickness = 0.4 mm. | 9 | L3 | CO1 | PO3 |
| | Determine; | | | | |
| | I) Chip reduction coefficient | | | | |
| | II) Shear angle | | | | |
| c. | Explain the following lathe operations: | | | | |
| | i) Taper turning operation | 9 | L2 | CO1 | PO1 |
| | ii) Threading operation | | | | |
| | iii) Knurling operation | | | | |

| P18IP44 | | | Page No 2 | |
|---------|--|----|------------|--|
| | UNIT - II | 18 | | |
| 2 a. | Why bench drilling machine is called sensitive drilling machines. Explain drilling machine (bench drilling machine) with a neat sketch. | 9 | L2 CO2 PO1 | |
| b. | With a neat sketch, explain the principle of quick return mechanism used in shaper. | 9 | L2 CO2 PO1 | |
| c. | Differentiate between shaper and a planer. | 9 | L3 CO2 PO1 | |
| | UNIT - III | 18 | | |
| 3 a. | Explain with a neat sketch upward milling and down ward milling operations. | 9 | L2 CO3 PO1 | |
| b. | With a neat sketch, explain principal parts of column and knee type milling machine. | 9 | L2 CO3 PO1 | |
| c. | What is simple indexing? With a neat sketch of simple indexing mechanism, describe the procedure of simple indexing method. | 9 | L2 CO3 PO1 | |
| | UNIT - IV | 18 | | |
| 4 a. | Explain the types of bonds used in grinding wheel. | 9 | L2 CO4 PO1 | |
| b. | With the help of sketch, explain surface grinding machine. | 9 | L2 CO4 PO1 | |
| c. | Discuss the following: | | | |
| | i) Balancing of grind wheel | 9 | L2 CO4 PO1 | |
| | ii) Wheel truing and dressing | | | |
| | UNIT - V | 18 | | |
| 5 a. | Explain the internal pull type broaching with a neat sketch. | 9 | L2 CO5 PO1 | |
| b. | Explain honing procedure with sketch. | 9 | L2 CO5 PO1 | |
| c. | Illustrate Rack cutter generating process with sketch. | 9 | L1 CO5 PO1 | |