U.S.N					



# P.E.S. College of Engineering, Mandya - 571 401

(An Autonomous Institution affiliated to VTU, Belgaum)

# Third Semester, M. Tech. - Mechanical Engineering (MCIM) Semester End Examination; Dec - 2016/Jan - 2017 Industrial Automation

Time: 3 hrs Max. Marks: 100

*Note*: i) Answer *FIVE* full questions, selecting *ONE* full question from each unit.

ii) Use of Statistical Quality Control Factor data sheets/Book is permitted.

# UNIT - I

- 1 a. Explain the USA principle of Automation.
  - b. Name the different categories of material transport equipments. Give their features and applications.
- 2 a. Explain briefly the strategies for Automation and Process Improvement.
  - b. Explain briefly the different AIDC technologies. Give their applications.

#### **UNIT - II**

- 3 a. List the distinct manufacturing systems along with their features.
  - b. Compare continuous control and discrete control.
- 4 a. What are the issues of planning and design of FMS? Explain briefly.
- b. List desirable features for selecting measuring devices.

### **UNIT - III**

- 5 a. Sketch and explain various part feeding devices.
- b. Write diagrammatic representation of shop floor control system. Explain the three important phases.
- 6 a. Sketch and explain different AGV systems.
  - Mention the different types of factory data collection systems along with their limitations.
     Explain briefly various structures of Automated FDCS terminals.

# **UNIT-IV**

- 7 a. List the SPC tools. Explain the Pareto diagram.
  - b. A precision industry manufactures leads for a drafting instrument. The diameter of eight samples (m) of size (n) 5 was measured for each part. Determine the control limits and show that the process is under control. The calculated values of  $\overline{X}$  and R values are given in Table 7b. The statistical constants are  $A_2 = 0.577$ ,  $D_3 = 0$ , and  $D_4 = 2.114$  for a sample size of 5.

Table 7b.

S	1	2	3	4	5	6	7	8
$\overline{X}$	2.008	1.998	1.993	2.002	2.001	1.995	2.004	1.999
R	0.027	0.011	0.017	0.009	0.014	0.020	0.024	0.018

10

10

10

10

10

10

10

10

10

10

10

10

10

<b>P1</b> :	<b>5MCIM331</b>	
8 a.	Explain cause and effect diagram with an illustration.	8
b.	What is CMM? Explain its construction.	12
	UNIT - V	
9 a.	Write the structure of MRP system and explain.	10
b.	What is CAPP? Explain Retrieval CAPP.	10
10 a.	List the outputs of MRP.	8
b.	What is the capacity planning? Explain the two stages clearly.	12